


Make sure that the wire can not be seen through the screw hole when putting the operation panel cover on the operation panel.



operation panel cover
operation panel

